

# Read Me

## System Software 7.4.10 PATCH 3

This version of our system software is available for the following gateways:

■ **1200wu.**

It contains the following changes that have been made since System Software 7.4.5 PATCH 7:

### 1.1 UMTS - Dial Out Ignores APM

(ID 7454)

An GSM capable UMTS modem may fail to include the necessary APM commands in the init sequence.

This problem has been solved.

### 1.2 UMTS - PINs mit 8 Zeichen Länge

(ID n/a)

The PIN of an UMTS/GSM card may now be up to 8 characters long.

